

Attn: _____

HIROSE ELECTRIC CO., LTD.
2-6-3 Nakagawa Chuoh, Tsuzuki-ku, Yokohama, Japan

Notice of DF51K(B)-SERIES Label Color Change

We are writing today to inform you that we will make some changes as shown in the subject for the reason described below. We will announce them in advance.

記

1. Products affected

DF51K Series Contact Gold Plated Pin Header (40 products in total)

- 1) DF51K(B)-**P-2DS (805)- 5 Products
- 2) DF51K(B)-**DP-2DS (805)- 14 products
- 3) DF51K(B)-**P-2DSA (805)- 6 products
- 4) DF51K(B)-**DP-2DSA (805)- 15 products

* Please refer to the attached file for details on the product name.

2. Changes

《Before》

DF51K(B) All specification Trays, Polybag Labels: White

《After》

- 1) DF51K(B) (805) Specification Tray, Polybag Label: Yellow
- 2) There is no change in the label color of trays and polybags of other specifications (white)

3. Reason for change

- 1) To prevent human error due to worker labeling errors during the assembly process
- 2) To manage separately during the work and appearance inspection in the process

4. Difference associated with a change in

There is no difference in product performance.

5. Change implementation period

Production will begin on September 14th with modified labels for eligible products.

6. If you should have any questions, please feel free to contact a Hirose business representative.

以上